



Over the Air System Updates

2022 TLX: Software Update Display Audio/Navigation Available

April 19, 2022


INTRODUCTION

This software contains system upgrades and enhancements that remedy a variety of operational errors.

INSTALLATION DETAILS

NOTE:

- For more information on how to do a software update, see System Updates in the online owner's manual or go to https://owners.acura.com/Documentum/ota/2022_TLX.pdf
- Due to the variations in the technology as well as how it is used and operates in different vehicles, your vehicle may not have experienced any of the symptoms or issues described below or only one (or some) of them. You should still obtain this software update.
- The software download will take about **30 minutes**.
- The vehicle can be used normally even while updates are in progress.
- Depending on your vehicle trim, some of the updates may not be applicable to your vehicle. Go to **System Updates** on the **Home** screen in your vehicle to start the update.



SOFTWARE VERSION D.1.6.2

Corrects the following potential intermittent errors:

- System automatic reboots after connecting a corrupted USB stick.
- The message Unfortunately, com.honda.auto.hars has stopped appears at ignition ON.
- Voice Recognition does not respond after ignition ON and remains inoperable.
- **Unfortunately, System UI has stopped** message appears after connecting a CarPlay device.
- **Navigation has stopped** message appears when route is set, and vehicle remains parked.
- **Navigation has stopped** message appears after viewing Route Overview.
- **com.honda.auto.transportservice** message appear cancelling navigation route.
- Unfortunately, com.honda.auto.diagnostics.service has stopped message appears for high traffic system network.
- **Navigation has stopped** message appears during normal system operation.
- **Unfortunately, com.honda.telephonyservice has stopped** message appears when changing to and from Bluetooth to CarPlay during an active phone call.
- **Navigation isn't responding** message appears after selecting Back on touchpad multiple times from View Routes screen.
- Bluetooth off and Unfortunately, Settings has stopped messages appear after ignition ON.
- **Navigation has stopped** message appears after ignition ON.
- Navigation has stopped message appears after selecting Continue Route at Resume Route pop-up.
- **Unfortunately, Android Auto has stopped** message appears when connecting an Android device for the first time while the vehicle is in motion, and selecting EXIT on the Android device.
- Unfortunately, com.honda.telephonyservice has stopped message appears at ignition ON.
- **Unfortunately, Phone has stopped** message appears when changing Bluetooth connection between two paired devices.
- At ignition ON, CarPlay is slow to connect when connecting device at system boot up.
- SiriusXM Favorites and Icons presets are empty after ignition ON.

Additions/Enhancements:

- Increased System pre-install timeout, to mitigate **Update Failed Code:57D** during software pre-installation.
- OTA updates fail and Dynamic Mode drive (IDS) animations do not work; after the vehicle's Fuel Injection ECU was replaced.
- Implemented Over the Air (OTA) WiFi only campaign system interface to connect to WiFi networks.
- Automatically transfer from Handset to handsfree mode when call enters "DIALING" state.
- Removed Bluetooth Hands Free Profile (HFP) dependency for allowing Android Auto to connect.
- Android Auto Security Patch for the Android Auto Projection AAP protocol library.

