




circuit
CUBES




GEARS GO GARAGE



XV-B6 MODEL INSTRUCTIONS






1





2





3





4





5



6




7




8







1





2






3





9





10






11




12




13





1



2




3





4

1





2




x2

1






2


1





2



3



4



14

