



Before You Begin

Read These Instructions Completely and Carefully



Upgrade Instructions: Knuckle Mount

STEP 1: Disconnect power from the luminaire and follow proper lockout/tagout procedures before beginning installation or maintenance.

STEP 2: Remove the existing luminaire. Dispose of the lamp(s) and ballast(s) per local requirements.

STEP 3: Wrap teflon tape around the knuckle mount nipple (A).

STEP 4: Secure the fixture to 1/2" NPS hole, junction box, or landscape post.


STEP 5: Plug any unused holes and seal thread with silicone.

STEP 6: Adjust the knuckle to aim the fixture where light is desired. (B)


STEP 7: Connect the fixture input leads (C) to the supply wire leads.



(C) Wiring Diagram - Fixture Without Photocell



(C) Wiring Diagram - Fixture With Photocell



STEP 8: Close the wiring enclosure.

NOTE: Take note **NOT** to pinch any wires when closing the fixture.

STEP 9: Power can now be restored to the fixture.

(800) 451-2606

6675 Parkland Blvd., Suite 100

Solon, Ohio 44139 USA

E-mail: Venture_Lighting@VentureLighting.com

VentureLighting.com





Avant que tu commences

Lisez ces instructions complètement et attentivement




Instruction de mise à niveau: Knuckle Mont


- 1: Coupez l'alimentation de l'appareil d'éclairage et de suivre les procédures de verrouillage / débranchement avant de commencer l'installation ou l'entretien.
- 2: Retirez le luminaire existant. Jeter la lampe (s) et le ballast (s) conformément aux exigences locales.
- 3: Enveloppez ruban téflon autour du mamelon de knuckle mont.
- 4: Fixer l'appareil à 1/2 "trou NPS, boîte de jonction ou paysage post.
- 5: Remplissez tous les trous non utilisés avec du silicone. Sceller fil avec du silicone.
- 6: Ajuster l'articulation de viser l'appareil où la lumière est souhaitée.(B)
- 7: Connecter les fils d'entrée de fixation (C) aux fils conducteurs d'alimentation.



(C) Schéma de câblage - Fixture Sans Photocell



(C) Schéma de câblage - Fixture Avec Photocell



- 8: Fermez le boîtier de câblage.

REMARQUE: Prenez note de ne pas pincer les fils lors de la fermeture du luminaire.

- 9: La puissance peut maintenant être restauré à l'appareil.

(800) 451-2606

6675 Parkland Blvd., Suite 100

Solon, Ohio 44139 USA

E-mail: Venture_Lighting@VentureLighting.com

VentureLighting.com

