




Qty
1


Type
TB-EM18WD-H1147-Ex




Ident-No. **7030381**



10...30 VDC



IP69K



1822H

Warning: Hazardous voltage can cause electrical shock and burns.
Disconnect power before proceeding with any work on this equipment.
Made in Germany
Hans Turck GmbH & Co. KG | Witzlebenstraße 7
45472 Mülheim an der Ruhr | Germany | www.turck.com

FCC/IC Digital Device Limitations

M/N: TB-EM18WD-H1147-EX
FCC ID YQ7-TBM18W
IC: 8821A-TBM18W
MVN: TB2863/3

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU.
The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU.
Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:




Qty
1


Type
TB-EM18WD-H1147-Ex/C53




Ident-No. **100036841**



10...30 VDC



IP69K



1922H

Warning: Hazardous voltage can cause electrical shock and burns.
Disconnect power before proceeding with any work on this equipment.
Made in Germany
Hans Turck GmbH & Co. KG | Witzlebenstraße 7
45472 Mülheim an der Ruhr | Germany | www.turck.com

FCC/IC Digital Device Limitations

M/N: TB-EM18WD-H1147-EX/C53
FCC ID YQ7-TBM18W
IC: 8821A-TBM18W
HMN: TB2863/3

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU.
The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU.
Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:





TURCK


Qty
1

Type
TB-M18-H1147

Ident-No. **7030001**



IP67



1622H

Warning: Hazardous voltage can cause electrical shock and burns.
Disconnect power before proceeding with any work on this equipment.
Made in Germany
Hans Turck GmbH & Co. KG | Witzlebenstraße 7
45472 Mülheim an der Ruhr | Germany | www.turck.com

FCC/IC Digital Device Limitations

M/N: TB-M18-H1147
FCC ID YQ7-TBM18W
IC: 8821A-TBM18W
HMN: TB2863/3

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU.
The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU.
Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

www.turck.com





TURCK

Qty
1


Type
TB-M18-H1147/C41



Ident-No. **7030588**



IP67



1622H

Warning: Hazardous voltage can cause electrical shock and burns.
Disconnect power before proceeding with any work on this equipment.
Made in Germany
Hans Turck GmbH & Co. KG | Witzlebenstraße 7
45472 Mülheim an der Ruhr | Germany | www.turck.com

FCC/IC Digital Device Limitations

M/N: **TB-M18-H1147/C41**
FCC ID **YQ7-TBM18W**
IC: **8821A-TBM18W**
HMN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU.
The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU.
Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

www.turck.com



TURCK

Qty
1

Type
TB-M18-H1147/C42

Ident-No. **100003695** **FW-V1.85**

CE

Cordset .../S2500

1 BN	+
3 BU	-
4 WH	Data
2 BK	Data

Cordset .../S2503

1 RD	+
3 BK	-
4 WH	Data
2 BU	Data

10...30 VDC
Ta:-25°C-70°C

Cordset .../S2501

1 BN	+
3 BU	-
4 BK	Data
2 WH	Data

IP67

1622H

Warning: Hazardous voltage can cause electrical shock and burns.
Disconnect power before proceeding with any work on this equipment.
Made in Germany
Hans Turck GmbH & Co. KG | Witzlebenstraße 7
45472 Mülheim an der Ruhr | Germany | www.turck.com

FCC/IC Digital Device Limitations

M/N: TB-M18-H1147/C42
FCC ID YQ7-TBM18W
IC: 8821A-TBM18W
HMN: TB2863/3

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU.
The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU.
Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

www.turck.com





TURCK

Qty
1


Type
TB-M18-H1147/C53

CE

Ident-No. **7030729**



IP67



1622H

Warning: Hazardous voltage can cause electrical shock and burns.
Disconnect power before proceeding with any work on this equipment.
Made in Germany
Hans Turck GmbH & Co. KG | Witzlebenstraße 7
45472 Mülheim an der Ruhr | Germany | www.turck.com

FCC/IC Digital Device Limitations

M/N: **TB-M18-H1147/C53**
FCC ID **YQ7-TBM18W**
IC: **8821A-TBM18W**
HMN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU.
The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU.
Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

www.turck.com