

How to Power DOWN a CB-Series Display with OPS PC Installed

1

Step 1: Select the 'Windows' button at the bottom left-hand corner of your screen




2

Step 2: Select the power button




3

Step 3: Select Shutdown and wait for the system to shut itself down



4

Step 4: When the following image is displayed press the power button located near the lower right-hand corner of the monitor



How to Power UP a CB-Series Display with OPS PC Installed

1

Step 1: Press the Power button located near the lower right-hand corner of the monitor to Power UP the Display and OPS PC. Once the display turns ON the OPS will begin the boot up process.

Note: You may need to log in with username and password.

