


SPARE PARTS LIST

Serial number	Accessories name	picture	Number:(PCS)	Serial number	Accessories name	picture	Number:(PCS)
1	canopy		1	6	Border accessories		3
2	Sling chain		1				
3	Main body connector		1	7	Lampshade		1
4	pull rod		3				
5	Main connecting rod		1				

INSTALLATION STEPS



- 1 First check if the spare parts list is missing.
- 2 Fix the hanging plate on the ceiling and adjust the holedistance of the hanging plate.
- 3 Connect the sponder to the lamp head main body and the hanging plate, and thread the main line from the sponder to the hanging plate.
- 4 Fasten the sponder on the hanging plate and lampshade
- 5 Connect the chain to the ceiling plate and the hanging plate, and thread the main line from the hanging plate to the ceilingplate.
- 6 Connect the black main line on the ceiling panel to the power line L and the white line n to the power line n. cover the wiringcap.
- 7 Fix the ceiling plate on the hanging plate, and adjust theappropriate height of the chain.
- 8 Just install the light source.

