



















ASSEMBLY INSTRUCTIONS




Part List

				
① x1Pc	② x1Pc	③ x1Pc	④ x1Pc	⑤ x1Pc
				
⑥ x1Pc	⑦ x1Pc	⑧ x2Pcs	⑨ x2Pcs	⑩ x1Pc
				
⑪ x1Pc	⑫ x1Pc	⑬ x1Pc	⑭ x1Pc	⑮ x2Pcs
				
⑯ x3Pcs	⑰ x2Pcs	⑱ x1Pc		

Hardware List

					
M6x50 Ax4Pcs	M6x35 Bx16Pcs	M6x30 Cx44Pcs	M6x25 Dx4Pcs	M6 Ex8Pcs	Fx4Pcs
					
Gx1Pc					




PLEASE BE CAREFUL. DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWER TOOLS !

Step 1




M6

Ex8Pcs



Step 2




Gx1Pc





M6x35

Bx4Pcs





Step 3

	
Gx1Pc	M6x35 Bx4Pcs





Step 4


	
Gx1Pc	M6x35 Bx2Pcs




Step 5





	
Gx1Pc	M6x30 Cx14Pcs




Step 6




	
Gx1Pc	M6x30 Cx20Pcs





Step 7

	
Gx1Pc	M6x30 Cx8Pcs





Step 8

	
Gx1Pc	M6x35 Bx6Pcs





Step 9



		
Gx1Pc	M6x50 Ax4Pcs	M6x30 Cx2Pcs

Step 10



		
Fx4Pcs	Gx1Pc	M6x25 Dx4Pcs

