











Assembly Instructions






<i>a</i>  2pcs	<i>b</i>  M6*30 8pcs	<i>c</i>  M5*12 32pcs	<i>d</i>  M6*15 18pcs
<i>e</i>  4pcs	<i>f</i>  3pcs	<i>g</i>  M4*25 3pcs	<i>h</i>  4pcs
<i>i</i>  M4*10 4pcs	<i>n</i>  1pcs		




1




$b*8$ $n*1$

2




3



$c*12$ $d*4$ $e*4$ $n*1$

4




$c*4$ $d*1$ $n*1$




5

FRONT




6

SIDE VIEW




7




$d*5$ $n*1$

8




9




$c*12$

10




11




$d*8$ $n*1$

12



13




h/i

$h*4$

$i*4$

14




FRONT


$c*4$



15



16




$f*3$


$g*3$




17




18



19



20



$a*2$

