





PARTS LIST




A		32+2set
B		M8*30 32+2pcs
C		M6*25 8+1pcs
D		M6*35 4+1pcs
E		M6*40 8+1pcs
F		2set
G		2set
H		4+1pcs
J		6+2set
K		32pcs
L		1pcs


Step 1 X2




Step 2 X2



Step 3 X2




Step 4



E 8pcs


Step 5 X2



F1=2pcs

F3=4pcs


Step 6



A 4set


B 4pcs

Step 7




A	4set	B	4pcs
---	------	---	------

Step 8




Step 9




A	8set	B	8pcs
---	------	---	------

Step 10







C 8pcs

Step 11



D 4pcs

Step 12 X2




F1=2pcs

F3=4pcs


H 4pcs

G 2set


Step 13



Step 14



Step 15



Step 16

