


E.X.DR.Z0



Xesar












Montageanleitung | Assembly manual | Montagehandleiding
Instructions de montage | Istruzioni di montaggio | Montážní návody
Montážne návody | Instrukcje montażu | Installationsanvisningar









E.X.DR.ZO.U.




W



L





Option





x = 40–50 mm

2 × 40 mm >>



x = 50–60 mm

2 × 50 mm >>



x = 60–70 mm

2 × 60 mm >>



x = 70–80 mm

2 × 70 mm >>



x = 80–90 mm







2 × 80 mm >>




x = 90–100 mm

2 × 90 mm >>








1




2







5




6




7




8




9



10



11



12

CHECK

