








+



Output 40 °C

	205	323
↓ 40 %	140 A 100 %	200 A 100 %
↓ 35 %	130 A 100 %	190 A 100 %


userdoc.kemppi.com

Mounting instructions

W025412 R00

Monteringsvejledninger – Montageanleitungen – Instrucciones de montaje – Asennusohje –
 Instructions de montage – Upute za montažu – Istruzioni di montaggio – Bevestigingsinstructies –
 Monteringsinstruksjoner – Instrukcja montażu – Adisionais de montagem – Instrucțiuni de montare –
 Инструкции по монтажу – Monteringsanvisning – Montaj talimatları – 安装指导